ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.:

Tabl

5-21000-OPS-GT Table of Contents, Rev 9

e of Contents, Rev 9 1 of 3

12/03/91

Effective Date: Organization:

**Environmental Management** 

## THIS IS ONE HOLUME OF A SIX VOLUME SET WHICH INCLUDES:

Page:

CONTROLLED VOLUME I: FIELD OPERATIONS (FO)

EG&G — ROCKY MORUMENTI GROUNDWATER (GW)

ENVIRONMENTAL MANAVOLUME IV: SURFACE WATER (SW)

This is a RED STATUME V: ECOLOGY (EE)

VOLUME VI: AIR (AP)

## TABLE OF CONTENTS FOR VOLUME III: GEOTECHNICAL

New Proc. No.	Old Proc. <u>No.</u>	<u>Title</u>	Rev. <u>No.</u>	Effective <u>Date</u>	
GT.01	3.1	Logging Alluvial and Bedrock Material	1	8/30/91	
DCN 91.01		Recording lithologic descriptions and securing core boxes		11/15/91	
DCN 91.02	<u>-</u>	Clarification of log approval for multi-use wells	1	12/03/91	
GT.02	3.2	Drilling and Sampling Using Hollow Stem Auger Techniques	1 .	8/30/91	
DCN 91.01	x	Unconsolidated core samples need not be peeled before sampling	1	10/29/91	
DCN 91.02		Correction of well location for low Alluvial thickness	1	11/6/91	
DCN 91.03		Ten foot long core barrels	1	11/15/91	
GT.03	3.3	Isolating Bedrock From the Alluvium with Grouted Surface Casing	1	8/30/91	
DCN 91.01		Change in criteria for cement grouting	1	10/02/91	
DCN 91.02		Grout procedure clarification	1	10/28/91	

REVIEWED FOR CLASSIFICATION/UCAL

Date.

A-SW-00110

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.: Page:

Effective Date: Organization:

5-21000-OPS-GT Table of Contents, Rev 9

2 of 3

12/03/91

**Environmental Management** 

New Proc. No.	Old Proc. <u>No.</u>	Title	Rev. No.	Effective <u>Date</u>
GT.04	3.4	Rotary Drilling and Rock Coring	1	8/30/91
DCN 91.01		Core barrel decontamination	1	10/22/91
DCN 91.02		Clarification of measuring tape decontamination requirements	1	10/29/91
DCN 91.03		Clarification of the use of super gel-x	1	12/03/91
GT.05	3.5	Plugging and Abandonment of Boreholes	1	8/30/91
DCN 91.01		Surface casing classification	1 .	10/22/91
GT.06	3.6	Monitoring Wells and Piezometer Installation	. 1	8/30/91
DCN 91.01		Industry Standard is 1 foot into Bedrock	1	10/15/91
DCN 91.02		For the Sitewide Program, Claystone Smearing does not seem to be a problem	1	10/15/91
DCN 91.03		Superseded by DCN 91.06	.1	11/08/91
DCN 91.04		Low Alluvial thickness wells	. 1	11/06/91
DCN 91.05		Superseded by DCN 91.08	1 -	11/06/91
DCN 91.06	v	Change in filter pack guidance	1	11/08/91
DCN 91.07		Decontamination for site-wide geological characterization	1	11/15/91
DCN 91.08		Figure replacement (GT.6-1)	1	11/15/91
DCN 91.09		Sampling with center bit drilling	1	12/03/91
GT.07	3.7	Logging and Sampling of Test Pits and Trenches	1	8/30/91



ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.: Page:

5-21000-OPS-GT Table of Contents, Rev 9

Effective Date:

12/03/91

Organization:

**Environmental Management** 

New Old Proc. Proc. No. No.		<u>Title</u>	Rev. No.	Effective <u>Date</u>
GT.08	3.8	Surface Soil Sampling	1	8/30/91
DCN 91.01		Clarification supplementation of GT.08 - Surface Soil Sampling	1	11/26/91
GT.09	3.9	Soil Gas Sampling and Field Analysis	1	8/30/91
GT.10	3.10	Borehole Clearing	1	8/30/91
GT.11	3.11	Plugging and Abandonment of Wells	,1	8/30/91
GT.15	3.15	Geophysical Borehole Logging	1	8/30/91
DCN 91.01		No Hole will be left Unlogged at the end of the day	1 1	10/15/91
GT.17	3.17	Land Surveying	1	8/30/91
GT.18	3.18	Surface Geophysical Surveys	1	8/30/91
GT.19	3.19	Field Gas Chromatographs	1	8/30/91
GT.20	3.20	Procedures for Soil Interstitial Water Sampling and Sampler Installation	1	8/30/91

## ENVIRONMENTAL MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

Procedure Number 5-21000-OPS-GT.6 Rev 1.

Page 1 of 1

Title Monitori	no Wells	भारतं निश्चलक	This is a		-	ate 11-25-91		DPS-67.06
Expires		<u> </u>		وفرقي المسترب	ision Required	Yes No	97.	09
Scope Lin	nitationE)	NURO INVIENTA		ENT DEPART	MEICZ			
	<del>-</del>	7186	is a RED (	Stamp				
item Number	Page	Step or Paragraph	Changes (Use DCN CONTINUATION SHEET for Additional Space)					
1	6 of 17	1	the alluvium bedrock/allu sample, con	i, a drive sam; ivial contact h ing will resum	ple may be taker as been reached e if indicated."	center bit needs to be after the interval is l. After a maximum farve 14 m 17 m	drilled to as of a one for n = 44 d	scentain if the at drive
aking a d	rive sam close to	ple immediate	ely after drillin erval will ensu	g with a cente	-		-	tact is believe
	ļ.	QAPM	X					-
W.B.	2/2/2	EOM	×	1 1 -	O'L huns	User	<del>  ×</del>	11/2=/21
n.bu	veracoral	\ EU/(		12/2/91				
pproval o	Respon	sible Manage	Pr Date	7/91	Is Posting Requ	i? If Yes, By What	Date?	Date Posted